


# WD 1412



[cm]  
v1/25.07.18  
I.D.



x2





12,5h



180  
HIC




48h


play  
vinici














14722745 x4    14725745 x4    14728745 x4    14731745 x4    142102 x16    142108 x16    142100 x16    141101 x4    141133 x4    141134 x4    142117 x2




141132 x5    144126 x2    141184 x1    141185 x1    141135 x1    141136 x1    141125 x2    141138 x1    141137 x2



142137 x1    141120 x8    141123 x4    141122 x4    141142 x12    142142 x4    142138 x3    145113 x1    142106 x1




142131 x2    145141 x1    B144 x2    141112 x1    992100 x2    P78-3 x4    994118 x3    145102 x1    144110 x1    B146-1 x2    994103 x1









994106 x1    992118 x1    992128 x1    145136 x1    145137 x1    145138 x1    145139 x1

AN112 8x50x222	PLYWOOD	HPL
	1x WD28	1x WD29
8x WD1	5x WD63	5x WD64
5x WD14-4	1x WD42	1x WD43
2x E39	1x WD40	1x WD41
1x E34	4x WD15	4x WD16
1xE35	1xCE6	1xCL6
4xWD67	2xWD33	2xWD34
4xWD68	2xWD76	2xWD77
3xWD2		
2WD14-3		
2xWD66		
2xE88		
6xWD52		





142109 x4









AN112 8x50















	PLYWOOD	HPL
2x	WD72	WD73
2x	WD74	WD75









play  
viaci







-	HDPE	HPL
4x	WD33	WD34










-	PLYWOOD	HPL
1x	WD40	WD41











1xWD14-2









4x WD63 WD64






play  
vinci





3xWD2





play  
Vinci






1xWD14-4





play  
vinci





992124 K2, K3



2x E39









K1




K2

K3




1x E34




1x E35




1x E34



-	PLYWOOD	HPL
2x	WD28	WD29





V001



vinci  
play

Art. №

— — — —  
year

2 0 1

— — — —  
EN 1176-1: 2017

Vinci Group Sp. z o.o.  
Reguły, ul. Królewska 5  
05-816 Michałowice  
POLAND

+48 42 203 24 99

www.vinci-play.com

www.babycam.pl

vinci play