









WD1434



v013
10.06.2022
D. P.
[cm]

vinci
play










[cm]



vinci
play







<p>16x M10x120 (K2) 18x M10x120 (K3)</p> <p>NOT INCLUDED </p>	<p>2x M8x120 (K2)</p> <p>NOT INCLUDED </p>
--------------------------------------------------------------------------	---------------------------------------------------



[cm]









vinci play





		PLYWOOD / HDPE		HPL	
62x	8x50 sxi	1x	WD33	1x	WD34
1x	E34 (K1,K3)	1x	WD19	1x	WD20
1x	1x E35 (K2)	1x	WD28 (S1)	1x	WD29 (S1)
1x	V001	1x	WD25	1x	WD26
		1x	WD72	1x	WD73
		1x	WD74	1x	WD75
		1x	WD113 (S6)	1x	WD114 (S6)
				1x	P061 (S6)

[cm]








PLYWOOD
WD74




HPL
WD75



PLYWOOD
WD72




HPL
WD73




8x50 sxi



141158



141104



8x50 sxi








1x P061 S6




[cm]

vinci
play



[cm]





vinci
play


PLYWOOD
WD25



HPL
WD26






8x50 sxi




[cm]



vinci
play







8x50 sxi




PLYWOOD WD28 (S1) HPL WD29


PLYWOOD WD113 (S6) HPL WD114



[cm]





vinci play



V001

Part No:
000000-
00000

000000-00000



[cm]

vinci
play